



Forane® 427A

Pressure-Temperature Chart

Saturation Temperature [°F]	Liquid Pressure [psig]	Vapor Pressure [psig]
-50	3.8	11.9
-45	0.1	9.0
-40	1.9	5.9
-35	4.1	2.4
-30	6.6	0.8
-25	9.3	2.9
-20	12.2	5.3
-15	15.4	7.9
-10	18.9	10.8
-5	22.8	14.0
0	26.9	17.5
5	31.4	21.2
10	36.3	25.4
15	41.5	29.9
20	47.2	34.7
25	53.3	40.0
30	59.8	45.7
35	66.8	51.9
40	74.3	58.7
45	82.3	65.6
50	90.8	73.3
55	99.9	81.5
60	109.6	90.3
65	119.9	99.6
70	130.8	109.6
75	142.4	120.3
80	154.6	131.6
85	167.6	143.7
90	181.2	156.4
95	195.6	170.0
100	210.8	184.4
105	226.8	199.6
110	243.6	215.7
115	261.2	232.7
120	279.7	250.6
125	299.1	269.5
130	319.4	289.5
135	340.7	310.5
140	362.9	332.6
145	386.1	355.9
150	410.3	380.4

Red numerals = inches Hg below 1 atm